



WaldoAir Ultra_50 Camera Kit Shipping and Storage List

- 1 - ??? hard shell case – contains all items below
- 1 – WaldoAir Ultra_50 camera (stored lens down)
- 1 – 12V battery pack
- 1 – AC charger with cord for battery pack
- 1 – WaldoAir C182 hard mount for airplane wing strut (requires A&P for mounting STC)
- 1 – C172 rubber spacer for wing strut mount
- 1 – WaldoAir camera mount hard spacer
- 2 – Banding straps – requires 7/16” deep well socket or wrench
- 2 – GPS antenna
- 2 – USB-A camera cable with collar
- 2 – Battery-to-camera cable (2 prong to 2 prong)
- 1 – Roll of 2-inch-wide gaffers tape
- 1 – Generic copy of STC
- 1 – Copy of WaldoAir manual
- 1 – Copy of Shipping List

In Aircraft logbook

- 1 – STC for specific aircraft
- 1 – Temporary W&B when Waldo unit is mounted